



# **The City of East Peoria Storm Water Management Plan**

December-2022

By



**Patrick N. Meyer & Associates, Inc.**

15109 West Bittersweet Court  
Brimfield, Illinois 61517  
Office/Mobile: 309-696-1935  
Email: [pmeyer@mtco.com](mailto:pmeyer@mtco.com)

## **Introduction**

The City of East Peoria was fortunate to be the recipient of \$30,000 of funding thru the Tri-County Regional Planning Commission (TCRPC) for enhancing the City's Storm Water Management System. Patrick N. Meyer & Associates, Inc. (PNMAI) was selected as the consultant from the attached Request for Qualifications. (Exhibit A)

## **Findings**

Cooperation amongst the City, TCRPC, and PNMAI was key for the success of this project. Initial conversations with the City produced a primary focus on the outfalls in one of the many bluff areas as noted on the map. (Exhibit B) TCRPC and PNMAI developed a list of attributes (Exhibit C) to be collected and the inventory commenced. Some of the attributes are purely characteristics of the material, while other attributes were collected for IEPA's NPDES (Illinois Environmental Protection Agency's National Pollutant Discharge Elimination System) purposes. PNMAI was also able to collect photographs of each outfall. As outfalls were being collected, PNMAI was fortunate to be able to collect other missing information for the Storm Water Management System. Inventory of the storm water features proved to be tedious and dangerous at times. Outfall inventory challenged the staff with thick brush and steep slopes. Traffic was also a concern on busier streets. PNMAI was able to collect over 300 outfalls. Most notably, there were four attributes that might signal immediate action.

A-Level of Erosion

B-Televise

C-Buried

D-Pipe Condition

The Level of Erosion was classified as such. The approximate percentage of the total collected is also noted.

Level 1-Severe Erosion (>5 ft)	~10% of all outfall were Level 1
Level 2-Medium Erosion (1-5 ft)	~25% of all outfall were Level 2
Level 3-No erosion, fully protected	~65% of all outfall were Level 3

This is likely the most important attribute. The Level 1-Severe Erosion sites were the most concerning. Some outfalls were noted to have up to 30 ft of erosion present. Some of these severely eroded spots were dangerously close roadways and/or residential/commercial buildings. We expect to further this discussion with a City/TCRPC/PNMAI field trip to the high priority severely eroded locations. The highest priority Level 1-Severe Erosion sites will likely need to be addressed with stone riprap and heavy equipment. Some Level 1-Severe Erosion and most Level 2-Medium Erosion locations could be addressed with log check dams. Exhibit D typifies erosion issues. Exhibit E denotes past photographs of riprap projects. Exhibit F includes information and examples regarding log check dams.

Televising and Buried were also noted attributes. PNMAI identified both of these attributes since some of the pipe locations were either unknown as far as direction or they were buried. The City could utilize this list to perform further investigation to enhance the inventory. A photograph of a buried pipe is in Exhibit G.

The last attribute that might require immediate action is the Pipe Condition. PNMAI noted the conditions of pipes as to whether they were rusted and/or they had holes. Pipe Condition concerns occurred mostly in Corrugate Metal Pipes (CMP). The history of CMPs began with installation in the 1970's. CMPs have traditionally been less cost for material and for installation purposes. However, they are believed to have a 40 year life span. We are now 50 plus years since the first installation. The harsh Midwest winters promote the necessity of salt on the roads; the salt also takes its toll on the metal of the CMPs. Many of the Level 1 Erosion spots listed above were a cause of CMP failures. It would seem proactive for the City to identify these CMPs and pre-empt failures of Level 1-Severe Erosion by investing in pipe-

rehabilitation such as CIPP (Cured In Place Piping). CIPP is simply installing a liner in an existing pipe without digging. See **Exhibit H** for an example of a deteriorated CMP. **Exhibit I** contains CIPP projects.

### **The Future-A Plan of Action**

Patrick N. Meyer & Associates, Inc. suggests the following plan of action regarding the City of East Peoria's Storm Water Management System.

1. Field Trip to physically see the high priority Level 1-Severe Erosion locations. Identify funding to address the high priority Level 1-Severe Erosion locations. **Exhibit J** identifies the top 10 of 30 high priority projects with approximately \$1.2 million. This exhibit also includes location maps and photographs.
2. Establish a schedule for City staff or contractors to televise outfall pipes (including the ones noted in the inventory as Televised and Buried), establish a condition of the pipes and a priority for CIPP. Establish funding for this task.
3. Seek funding to continue the inventory of the Storm Water Management System. There is approximately 70% percent of the City's storm water infrastructure to be inventoried.



## **Exhibit A**



# **Request for Qualifications**

## **East Peoria Stormwater Planning Management**

---

Tri-County Regional Planning Commission requests statements of qualifications from qualified firms to provide professional services to assist updating the City of East Peoria's Stormwater Management System.

Statements of Qualifications will be accepted until 4:00 pm, June 17, 2022. Statements of qualifications received after that date and time will not be considered.

### **Background**

Tri-County Regional Planning Commission (TCRPC) of Peoria, Illinois proudly serves Peoria, Tazewell, and Woodford counties as the "Steward of the Regional Vision." TCRPC studies the needs and conditions of the region and develops strategies that enhance the area's communities. TCRPC offers a forum for leaders of area government to define regional issues, set regional goals, and cooperatively implement plans.

TCRPC is the Metropolitan Planning Organization (MPO) for the Peoria-Pekin urbanized area. As the MPO, TCRPC carries out the continuing, cooperative, and comprehensive (3-C) transportation planning process required by law. TCRPC carries out this process by preparing regional plans and programs with the assistance of an MPO Technical Committee.

The MPO receives federal funding from the U.S. Department of Transportation. A portion of the FY 2022 allocation has been set aside for this project. The initial proposed compensation for this project is \$30,000. Due to the federal funding source, all work related to the project must be completed by December 31, 2022.

### **Project**

There are many locations throughout the City of East Peoria where erosion and sedimentation create problems for surface transportation. The project goal is to collect accurate data on storm sewer outfalls to help access the degree to which the City's storm sewer infrastructure contributes to the erosion and siltation issue. The analysis will factor in other contributors, such as topography, filling operations, normal sheet drainage, or poor property management.

There are areas in the city where storm sewer pipes become plugged with siltation, causing stormwater and silt to flow over the streets and flood the roadways. Some of these locations have speed limits of 40mph and surprise traffic with water and debris in the roadway.

In some cases, it is known the siltation is coming from private property. In other cases, it is natural siltation, but the degree to which the city outfalls are contributing to the problem is unknown. The City's contribution to this issue will be assessed by expanding our inventory and knowledge of the storm sewer infrastructure. The ultimate goal is to develop a plan to mitigate the siltation and flooding along streets to improve roadway safety.

With funding provided by Tri-County Regional Planning Commission, the City of East Peoria is requesting a consultant to aid in their stormwater asset inventory initiative. East Peoria has completed approximately 75% of its existing stormwater infrastructure and is seeking assistance with areas within the city with the most need along the bluffs. These areas are but are not limited to Illini Heights, Bloomington Rd, Pekin Ave, Fondulac Dr, Springfield Rd, and Washington St.

This project would inventory storm sewer infrastructure in selected areas, such as outfalls, pipes, inlets, maintenance holes, and flow. The inventory would include the collection of relevant attributes, such as grate size, pipe size, material, location description, photo attachments, and notes. Along with the data collection, the selected consultant will perform an analysis to understand the extent of the sedimentation and erosion issues. The goal is to ensure that the City's stormwater management system is up to date and includes all relative infrastructure and attributes.

Ideally, televising pipes to narrow down pipe types among concrete, PVC, and metal would be included to aid in understanding problem areas within the existing stormwater system and mitigate any problems.

### **Scope of Services**

Negotiation of the final scope of services will occur upon consultant selection, but the project should include the following elements.

1. Storm Sewer Infrastructure Inventory
  - a. Identify areas of concern regarding missing storm sewer infrastructure.
  - b. Inventory storm sewer infrastructure in a GIS database, including relevant attributes such as pipe sizes, material, digital photographs, erosion severity, illicit discharge, etc.
2. Storm Sewer Assessment
  - a. Analyze existing storm sewer data and GIS data collected to understand the extent of the erosion and sedimentation issues impacting surface transportation.
  - b. Identify areas of concern regarding outfall locations.
3. Develop Cost Estimates for Future Project Work
  - a. Develop a budget to inventory the remaining areas of the city.
  - b. Develop a budget to identify future pipe televising probability.
  - c. Develop a budget to review available property/easement data to assess access, safety concerns, and topography. Prepare a template for site access if no easements exist.
  - d. Develop preliminary cost estimates, including cultural and natural review and environmental documentation.

Please note that the City of East Peoria is open to utilizing their GIS Intern for assisting in data collection. TCRPC is able to supply East Peoria's GIS Intern with one Trimble R2 GPS Unit with a Trimble VRS Network Subscription and assist with processing the storm sewer data.

## **Deliverables**

This contract will result in the following deliverable:

- GIS Database of Storm Sewer Infrastructure
- Analysis and conclusion report
- Cost estimate for future project expansion

## **Submittal Contents**

TCRPC will only consider submissions limited to 15 pages (not including resumes) and containing the following:

- Name, address, telephone number, email, and website of firm.
- A Statement of Qualifications of:
  - The firm and any subcontractors (if any).
  - The lead team member; and
  - The individuals to be assigned to the project.
- At least three (3) examples of similar projects the firm has completed in the last 5 years.
- Business references from these projects, including client's name and telephone number shall be included; and
- Identification of any potential subcontracted services as necessary.

Please submit two (2) physical copies and one (1) digital PDF with all submittals.

All submittals shall be sealed and identified as East Peoria Stormwater Management and addressed to:

Michael Bruner  
Planner  
Tri-County Regional Planning Commission  
456 Fulton Street, Suite 401  
Peoria, IL 61602

## **Contract Development**

Tri-County Regional Planning Commission will enter into a contract for professional consulting services based on a fixed-price to the selected consultant for a Scope of Services to be negotiated and finalized once the consultant is chosen. Incremental payments to the consultant will be made at the completion of major tasks with a "not to exceed" contract amount. Ten (10) percent of the contract price will be held as final payment upon delivery of the final products. The exact payment schedule will be negotiated and determined as part of the contract.

TCRPC is not liable for any costs incurred by a consultant in responding to this Request for Qualifications or for any costs associated with discussions required for clarification of items related to this RFQ.

The contract shall not be considered executed unless signed by the authorizing representative of TCRPC.

## **Selection Process**

TCRPC reserves the right to accept or reject any or all statements of qualifications. All submittals become the property of TCRPC upon receipt. TCRPC will evaluate each statement of qualifications according to the following factors and 100-point scale:

1. **(25 points) Experience and Technical Competency**  
The consultant's response should reflect qualifications and experience necessary to successfully develop and execute a Scope of Services. Reviewers will also assess the applicability and relevance of the consultant's experience and previous projects.
2. **(25 points) Familiarity with Project Type**  
The consultant's response must demonstrate a level of familiarity with the proposed project and an understanding of the planning challenges posed by the project.
3. **(25 points) Record of Success**  
The consultant's response should demonstrate success on similar projects and provide examples of similar work.
4. **(15 points) Local Knowledge**  
The consultant should demonstrate familiarity with the City of East Peoria and Greater Peoria in their response.
5. **(10 points) References**  
The consultant's response should include at least 3 references, with contact information.

All submittals will be reviewed by a committee made up of representatives from TCRPC and The City of Peoria. All statements of qualifications will be scored and ranked; however, the committee IS NOT bound to select the highest-scoring submittal. TCRPC reserves the sole right to invite one firm to the contract development stage or to reject all candidates that submit.

## **Project Schedule**

- **June 3, 2022** – Request for Qualifications is announced
- **June 17, 2022** – Deadline for submittal of statement of qualifications
- **Week of June 20, 2022** – TCRPC & City of East Peoria evaluate responses and select consultant; TCRPC approves contract with consultant
- **July 1, 2022** – Work begins
- **December 31, 2022** – All project work is completed by this date

## **Compliance with Laws**

The selected firm agrees to be bound by all applicable Federal, State, and Local laws; regulations; and directives as they pertain to the performance of the contract.

## Questions

TCRPC staff will answer all questions related to this RFQ until 4:00 pm, June 15, 2022. All questions and answers will be posted publicly on TCRPC's website. Questions should be addressed to staff at [rfp-rfq@tricountyrpc.org](mailto:rfp-rfq@tricountyrpc.org).

## **Exhibit B**



A map showing two specific areas highlighted with blue dashed cloud-like borders. The 'Fondulac/Highview area' is located in the upper-middle section, adjacent to a large blue lake. The 'Springfield area' is located in the lower-middle section. Both areas are filled with a light green color and contain a network of streets. A black line with an arrow points from the text label to the corresponding area on the map.


Fondulac/  
Highview  
area

Springfield  
area



## Map of Project Area

(green dots reflect outfalls collected)



## **Exhibit C**

### **List of Attributes**

OBJECTID	Material Type	Diameter (inches)	Date Inspected	Outlet Name	Location	Pipe Condition	Erosion Condition
232	Corrugated Metal	15	11/12/2022 19:29			Very Poor	1 - Severe Erosion (>5ft)

Depth of Erosion (ft)		VI - Color	VI - Odor	VI - Clarity	VI - Float	VI - Settled Solids	VI - Suspended Solids?
30 ft	30	Clear	No	Clear	No	No	No

VI - Foam?	VI - Oil Sheen?	VI - Other Commer	Field Inspected?	Headwall?	GlobalID	Notes	Headwall Notes
No	No	The pipe has extre	Yes	No	0f44b5ce	Pipe sections ar	None

Ownership	Status	Televis	Buried	x	y		
Public	Completed	No	No	-89.5446343	40.6339		

## **Exhibit D**



example of  
Level 1-Severe  
Erosion-pipe  
was rusted  
through and  
caused erosion  
on a very steep  
hill





example of  
Level 1-Severe  
Erosion-water  
eroded at end  
of pipe causing  
pipe to no  
support  
underneath-  
then pipe  
breaks off  
causing more  
erosion and  
repeating the  
process






example of  
Level 1-Severe  
Erosion-100 ft  
elevation  
change from  
the top of the  
pipe to the  
bottom of the  
ravine







apparent  
pieces of pipe  
that have  
broken off  
over the  
years.

gutter drains  
on hillside that  
need to go to  
the bottom of  
the hill



example of  
Level 1-Severe  
Erosion-30 ft  
depth





## **Exhibit E**

example of  
dangerous  
ravine  
stabilization  
requiring riprap,  
specialized  
machinery, and  
highly skilled  
workers-125 ft  
elevation  
change from  
top of hill to  
bottom of hill





example of dangerous ravine stabilization  
requiring riprap, specialized machinery,  
and highly skilled workers-125 ft elevation  
change from top of hill to bottom of hill





example of  
dangerous  
ravine  
stabilization  
requiring  
riprap,  
specialized  
machinery,  
and highly  
skilled  
workers-125 ft  
elevation  
change from  
top of hill to  
bottom of hill





final product of  
ravine  
stabilization-  
nearly 250 tons  
of riprap





## **Exhibit F**



newly  
constructed  
log check  
dam---10 ft  
high





newly  
constructed  
log check  
dam---6 ft high





newly  
constructed  
log check  
dam---4 ft high





3 years old---  
gained back 2  
ft of material






3 years old---  
gained back 2  
ft of material






# FACT SHEET



EXISTING GROUND



## WHAT:

Small stack of logs placed in zero order or first order drainage ways that carry surface water flow only after storm events or snow melt.

## WHY:

The logs are stacked to stabilize the slope grade, slow the water runoff, store a small amount of sediment, and reduce erosion.

## WHERE:

Appropriate in ditches, swales, overland flow areas. Stabilizers can be placed in series down a slope such that the bottom of the upstream stabilizer is just above the top of the next downstream stabilizer. Do not place in watercourses, streams or major drainage ways.

## DETAILS:

Maximum height should be approximately 3' to 4' with a 1' notch or V depression in the center to control flow.

## MAINTENANCE:

Inspect during and after large storms or extended periods of rain. Inspect for erosion around top edges, scour and infilling. Re-arrange or remove logs to correct scour issues.

## EXAMPLES:

Log check dams have been constructed and are available for viewing at the Camp Wokanda Demonstration Site.

Reference: USFWS Low Tech V Log Check Dam Standard

CLIENT:		TITLE:		PROJECT NO.	
TRI-COUNTY REGIONAL PLANNING COMMISSION FOREST MANAGEMENT SPECIFICATIONS		LOG GRADE STABILIZER "LOW TECH "V" LOG CHECK DAM"		07-167	
				SHEET OF	
 <b>CHRISTOPHER B. BURKE</b> ENGINEERING LTD. 202 NE Madison Avenue Suite 301 Peoria, Illinois 61602 (309) 676-9000		DSCN.		SCALE:	
		DWN.		DATE:	
		CHKD.		PLOT DATE:	
				7/20/2007	
DRAWING NO.					

**pmeyer@mtco.com**

---

**From:** Figge, Gene <Gene.Figge@Illinois.gov>  
**Sent:** Wednesday, January 9, 2019 11:09 AM  
**To:** Patrick Meyer; Bennett, Todd; Thorp, Jason  
**Cc:** Huson, Todd; Jungles, Paul  
**Subject:** RE: [External] FW: Log Check Dams

I am fine with it, but that is not something you will ever get a formal blessing on from the Agency. That is the sort of thing we just do not do because as inspectors we are not omnipotent. All you will ever get is something along the lines of "it appears to be in compliance with the Act and Regulations." So, it appears to be in compliance with the Act and Regulations when executed in this manner.

Gene Figge  
Environmental Protection Specialist  
412 SW Washington  
Peoria, IL 61602  
309/671-3070

---

**From:** pmeyer@mtco.com <pmeyer@mtco.com>  
**Sent:** Wednesday, January 09, 2019 11:04 AM  
**To:** Bennett, Todd <Todd.Bennett@Illinois.gov>; Figge, Gene <Gene.Figge@Illinois.gov>; Thorp, Jason <Jason.Thorp@Illinois.gov>  
**Cc:** Huson, Todd <Todd.Huson@Illinois.gov>; Jungles, Paul <Paul.Jungles@Illinois.gov>  
**Subject:** [External] FW: Log Check Dams

Todd/Gene/Jason...did you have any more thoughts regarding our log check dams...I would really like to get your blessings from both land and storm water...

Sincerely,

Patrick

Patrick N. Meyer & Associates, Inc.  
Patrick N. Meyer, P.E., M.B.A.

---

**From:** [pmeyer@mtco.com](mailto:pmeyer@mtco.com) <[pmeyer@mtco.com](mailto:pmeyer@mtco.com)>

**Sent:** Wednesday, October 10, 2018 11:20 AM

**To:** 'Bennett, Todd' <[Todd.Bennett@Illinois.gov](mailto:Todd.Bennett@Illinois.gov)>; 'Figge, Gene' <[Gene.Figge@Illinois.gov](mailto:Gene.Figge@Illinois.gov)>; 'jason.thorp@illinois.gov' <[jason.thorp@illinois.gov](mailto:jason.thorp@illinois.gov)>

**Subject:** Log Check Dams

Todd/Gene/Jason...

As we discussed, we have been recommending log check dams as a good way to naturally deter erosion. Here is an example standard and a real life example. We have seen a significant amount of sediment trap behind the log check dams in a relatively short amount of time...as much as 1 ft in a 2 years. I believe Todd supports the use of these...I wanted to send the attachments to Gene and Jason to help you realize the benefit. Please comment back.

Sincerely,

Patrick

Patrick N. Meyer & Associates, Inc.

Patrick N. Meyer, P.E., M.B.A.

State of Illinois - CONFIDENTIALITY NOTICE: The information contained in this communication is confidential, may be attorney-client privileged or attorney work product, may constitute inside information or internal deliberative staff communication, and is intended only for the use of the addressee. Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify the sender immediately by return e-mail and destroy this communication and all copies thereof, including all attachments. Receipt by an unintended recipient does not waive attorney-client privilege, attorney work product privilege, or any other exemption from disclosure.

## **Exhibit G**



buried outfall





## **Exhibit H**






example of  
corrugated  
metal pipe that  
is rusted  
through-factors  
of deterioration  
include age  
and salt on  
metal



## **Exhibit I**



lining avoided  
digging a new  
road surface

existing CMP  
pipe that had  
holes in it

lining material  
inside the  
existing CMP





existing CMP  
pipe that had  
holes in it

lining material  
inside the  
existing CMP





lining material



10/12/06 08:17  
191.3 FT.  
MH START: 11694  
MH STOP: 11613

lining material  
creating a  
seamless pipe  
inside the  
existing  
deteriorated  
pipe



## **Exhibit J**

## High Priority Projects

\$1,175,000

OBJECTID	Material Type	Diameter (inches)	Pipe Condition	Erosion Condition	Depth of Erosion (ft)	Cost	Location	VI - Other Comments?	Notes
232	Corrugated	15	Very Poor	1 - Severe Erosion (>5ft)	30 ft	\$ 200,000	Off of Harvey	The pipe has extremely SEVERE erosion occurring, up to 30 ft	Pipe sections are coming apart and is in proximity of building
10	Corrugated	18	Very Poor	1 - Severe Erosion (>5ft)	20ft plus	\$ 200,000	Off of Centennial Hill	The pipe has bad rust and is broken near the bottom of the pipe... Also, the end section fell off	There is extreme erosion on the hillside behind the pipe, creeping towards the road... Also, not completely sure on the pipe size, somewhere close to a 18" pipe
92	Corrugated	24	Very Poor	1 - Severe Erosion (>5ft)	14-15 ft	\$ 75,000	Off of Illini	Severe erosion up to 14-15 ft and little to no standing water	The pipe itself is in good shape but parts of the pipe have come off due to erosion
194	Corrugated	18	Poor	1 - Severe Erosion (>5ft)	15 ft	\$ 75,000	Off of Terrace Ln	This outfall has SEVERE erosion	The pipe is rusting
260	Steel	13	Poor	1 - Severe Erosion (>5ft)	15 ft	\$ 75,000	Off of Maria	Televised!	The pipe is rusted
214	Corrugated	15	Very Poor	1 - Severe Erosion (>5ft)	10-12 ft	\$ 75,000	Off of Springfield Rd	The pipe has severe erosion up to 10-12 ft	The pipe is rusting bad causing severe erosion
263	Corrugated	12	Fair	1 - Severe Erosion (>5ft)	12	\$ 75,000	Off of Maria	There is major erosion at the outfall due to break in pipe	Pipes been broken in places and is eroding
94	Corrugated	18	Very Poor	1 - Severe Erosion (>5ft)	9-10	\$ 150,000	Off of Illini	9-10 feet of erosion, no standing water	Belly of pipe is completely rusted out and is completely falling apart as it's coming off the hillside.
166	Corrugated	24	Poor	1 - Severe Erosion (>5ft)	10 ft	\$ 150,000	Off of Oakwood	Bad erosion around the outfall	The pipe bottom is rusted
261	Corrugated	10	Poor	1 - Severe Erosion (>5ft)	10 ft	\$ 100,000	Off of Maria	Severe erosion occurring outside the outfall pipe	Rusty with holes, may be broken off in the pipe



## High Priority Projects

OBJECTID	Material Type	Diameter (inches)	Pipe Condition	Erosion Condition	Depth of Erosion (ft)	Cost	Location	VI - Other Comments?	Notes
262	Corrugated	10	Poor	1 - Severe Erosion (>5ft)	10 ft			Severe erosion and pipe is rusted	Bad erosion and erosion creeping up on homeowners garage approx 10 ft away
173	Corrugated	18	Good	1 - Severe Erosion (>5ft)	8 ft			There is erosion approx 8ft and no standing water in the outflow pipe	The pipe itself is in good shape with no visible damage
227	Corrugated	24	Fair	1 - Severe Erosion (>5ft)	7-8 ft			There is severe erosion and standing water outside the pipe	The pipe is in decent shape
305	Corrugated	12	Fair	1 - Severe Erosion (>5ft)	8 ft			There is some severe erosion outside the pipe, approx 8 ft... no standing water	The pipe is in decent shape with no visible damage, but there is some severe erosion happening
323	Concrete	24	Very Poor	1 - Severe Erosion (>5ft)	7-8 ft			There is severe erosion around the outfall and going down the ditch	The end pipe section has come off and erosion is occurring at the separation... more pipe section will fall off as the erosion continues to eat towards Pinecrest Dr to the East
98	Concrete	24	Good	1 - Severe Erosion (>5ft)	7			Several sections of pipe is broken off eroding hillside approaching Illini Dr	Outflow not directly visible, but can see rest of the pipe and can hear water flow
220	Corrugated	18	Good	1 - Severe Erosion (>5ft)	6-7 ft			There is some severe erosion occurring here, approx 6-7 ft	The pipe itself looks to be in decent shape
165	Corrugated	15	Poor	1 - Severe Erosion (>5ft)	6 ft			There is erosion approx 6ft with no standing water	The CMP pipe has a rusted bottom



## High Priority Projects

OBJECTID	Material Type	Diameter (inches)	Pipe Condition	Erosion Condition	Depth of Erosion (ft)	Cost	Location	VI - Other Comments?	Notes
181	Corrugated	15	Good	1 - Severe Erosion (>5ft)	6 ft			The pipe is severely damaged... broken off in many places	Has some erosion around the outfall
292	Corrugated	12	Fair	1 - Severe Erosion (>5ft)	6 ft			There is about 6 ft of erosion and the pipe is hanging out 20 ft in	The pipe is in decent shape with no visible damage
299	Corrugated	12	Excellent	1 - Severe Erosion (>5ft)	6			sinkhole	
306	Corrugated	15	Very Poor	1 - Severe Erosion (>5ft)	5-6 ft			The pipe has erosion occurring down the hillside, approx 5-6 ft... no standing water	The pipe is in pieces coming down the hillside and is causing severe erosion
40	Corrugated	18	Poor	1 - Severe Erosion (>5ft)	3-5 ft			Labeled as a 1 because of proximity to houses... The bottom of the pipe in the belly of the gully, there is another major break in the pipe, causing a hole to start eroding... also erosion under the pipe as it goes down the hill	Goes from a 18" CMP to a 18" Corrugated Plastic Pipe... the CMP pipe is in decent shape, but as it switches to the Plastic pipe to dump down the hill, there are multiple breaks in the pipe, causing water to erode underneath the pipe from the break points
215	Other		Poor	1 - Severe Erosion (>5ft)	5 ft			This is not a pipe, but there is erosion from stormwater happening here	There is bad erosion here, affecting road
277	Corrugated	15	Poor	1 - Severe Erosion (>5ft)	3 ft			There is some erosion outside the pipe, approx 3 ft... there is some severe erosion by part of the exposed pipe at the top of hill	TELEWISE! Pipe may be broken or damaged between the inlet and the outfall



## Object ID 232-Off of Harvey Ct














## Object ID 10-Off Centennial Dr



**High  
Priority  
\$200,000**












## Object ID 92-Off Illini Dr



**High  
Priority  
\$75,000**











## Object ID 194-Off Terrace Ln









## Object ID 260-Off Maria St














## Object ID 214-Off Springfield Rd










## Object ID 263-Off Maria St










## Object ID 94-Off of Illini Dr



**High  
Priority  
\$150,000**












## Object ID 166-Off of Oakwood Rd













## Object ID 261-Off of Maria St









